

## State of Utah DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director 355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180-1203 801-538-5340 801-359-3940 (Fax) 801-538-5319 (TDD)

September 15, 1995

TO:

Minerals File

FROM:

Tony Gallegos, Reclamation Engineer All

RE:

Site Inspection, Barrett Mines Inc., Beaver Dam Wash Project, S/053/010,

Washington County, Utah

Date of Inspection:

September 13, 1995

Time of Inspection: Conditions:

1525 - 1545 Clear and hot

Participants:

Larry Gore (observer) - BLM; Tony Gallegos, Tom Munson - DOGM

Purpose of Inspection: To examine the mine site while in the area.

This inspection was not scheduled, so the operator had not been contacted in advance. The mining disturbance is a flat area located on the south side of the main access road. The pad area has minimal vegetation at this time. Located on the site were a number of large wooden ties, some 6" diameter rubber pipe, some smaller diameter steel pipe and then some other sections of 4" diameter steel pipe. The perimeter of the pad area has a number of small soil piles. These piles probably contain soils graded off to make the area level.

There were no signs of recent mining activity or any recent activity at the site, other than the flat pad area being used as a turn around. Photographs were taken of the general site.

This file could possibly be closed after reclamation at this site is considered complete. We need to contact SITLA to see what the status of the mineral lease is.

jb

cc:

Robert Robison, Operator

Will Stokes, SITLA

S053010.ins







